



MST GROUP LTD (HK)

Final Random Inspection Report

ADD: UNIT 710, 7F, BAOLI BUILDING, NANHAI ROAD, NANSHAN DISTRICT SHENZHEN, P.R. CHINA 518054
 Tel: 86-755-26421993 FAX: 86-755-26429496 Email: info@mstradechina.com Website: www.mstradechina.com

EXECUTIVE SUMMARY AND INSPECTION STANDARD:

Client:	MST Group	Contact person:	×××××				
PO.No.:	H-SCS-080201	Description:	Plough machine				
Supplier:	××××××	Contact person:	Cathy				
Insp. Location:	××××××	Time of insp.:	1 st × 2 nd 3 rd				
Order No.	Item No.	Order Qty	Available Quantity			inspect Qty	
			Packed	Not packed	Not finished		
H-SCS-080201		120	20	100	0	120pcs	
Inspection standard: <i>ANSI/ASQC Z1.4-1993</i>				Sample Size: 120pcs			
Sampling plan: <i>Single, Normal</i>				Critical	Major	Minor	
Inspection level: II				AQL:	0	1.5	4.0
AQL: Critical: Not Allowed.				Defects Found:	0	0	4
				Max. Allowed:	0	5	10
Sample carton No.: No carton No. for available.							

Overall conclusion

Inspection criteria	Result	Comments
Quantity available:	<input checked="" type="checkbox"/> conformed [] not conformed	
Workmanship:	<input checked="" type="checkbox"/> conformed [] not conformed	
Test:	<input checked="" type="checkbox"/> conformed [] not conformed	
Data measurement:	<input checked="" type="checkbox"/> conformed [] not conformed	
Labeling:	<input checked="" type="checkbox"/> conformed [] not conformed	
Packing/shipping mark:	<input checked="" type="checkbox"/> conformed [] not conformed	
Result:	<input checked="" type="checkbox"/> Acceptable [] Reject [] Pending	
Special remark:		

Inspector signature: Yu Xinjiang Date: Feb 18, 08 Vendor signature: _____ Date: _____

This report only reflects the truth of quality in this lots goods, based on statistical sampling procedure. Inspection is performed to the best of our ability and skills but without responsibility on our part, nor does it evidence shipment. www.mstradechina.com

PRODUCT AND DEFECTS PHOTO SHOW

<p>Master carton view:</p>	<p>Main marking:</p>															
																
<p>Side mark:</p>	<p>Open carton view:</p>															
 <table border="1" data-bbox="370 1192 646 1276"> <thead> <tr> <th>Модель</th> <th>Посадка</th> <th>шт</th> <th>Вес брутто</th> <th>кг</th> </tr> </thead> <tbody> <tr> <td>М0443</td> <td>75</td> <td></td> <td>78</td> <td></td> </tr> <tr> <td>Габариты(мм)</td> <td colspan="4">630*375*170</td> </tr> </tbody> </table>	Модель	Посадка	шт	Вес брутто	кг	М0443	75		78		Габариты(мм)	630*375*170				
Модель	Посадка	шт	Вес брутто	кг												
М0443	75		78													
Габариты(мм)	630*375*170															
<p>Instruction sheet:</p>	<p>Tools for assembly:</p>															
																
<p>Spare parts:</p>	<p>Metal frame for packing:</p>															



Side of metal frame:



Side of metal frame:



Side of metal frame:



Product after assembly:



Side of product:



Sticker on oil tank:



Sticker on machine:



Sticker on the metal frame:



Sticker on shield board:



sticker on the cover of the transfer band:



front of the machine:



Back of machine:



Level for left hand:



Level for right hand:



plough assembled



Plough assembly:



parts view:



Parts view:



Parts view:



reference No. Of the engine



axle of the front wheel:



embrace of the front wheel:



gear lever:



embrace on back of the machine:



bottom of the machine:



Wheels:



test of changing the velocity:



launching test:



test of the power rating for engine:



test of the power rating for engine



velocity testing of the transfer band:



Tough surface:

Dirty mark:



unable to return to exact position:



scratch mark: (surface not smoothly)



Finished products:



Packed products:



END